	Туре	Hits	Search Text
1	BRS	1	10/806533
2	BRS	1	10/806838
3	BRS	1	10/806538
4	BRS	1	10/806838
5	BRS	1	10/806838
6	BRS	1	S5 and (clamp\$4 same (posit\$5 adjust\$5) same (motion\$4 mov\$6 dimention\$4 coax\$5 abut\$5))
7	BRS	1	S5 and (motion\$4 near12 mov\$6 same (dimention\$4 coax\$5) same (align\$5 abut\$5))
8	BRS	1	S5 and (motion\$4 near12 mov\$6) and (mov\$6 same (dimention\$4 coax\$5) same (align\$5 abut\$5))
9	BRS	1	S5 and (imag\$5 same (illumin\$5 detect\$5 noncoinciden\$5 coincident\$4 display\$5))
10	BRS	850677	<pre>(imag\$5 same (illumin\$5 detect\$5 display\$5))</pre>
11	BRS	1	S5 and (rotat\$4 same (align\$5 fiber\$1 fibre\$1))
12	BRS	359756	<pre>(rotat\$4 same (align\$5 fiber\$1 fibre\$1))</pre>
13	BRS	1	S5 and (electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)
14	BRS	1632	<pre>(electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)</pre>
15	BRS	3595	(fus\$5 splic\$4 weld\$4) near12 (fiber\$1 fibre\$1) same align\$5
16	BRS	63344	(fiber\$1 fibre\$1) same imag\$4
17	BRS	29	S10 and S12 and S14 and S16 and S17
18	BRS	23	S18 and (display\$4 screen\$3)
19	BRS	1	S5 and (motor\$1 actuat\$5) near12 (driv\$5 fiber\$1 fibre\$1)

	DBs	Time Star	- 1	Comments	Error Definition
1	US-PGPUB; USPAT; EPO; JPO; DERWENT	l .			
2	US-PGPUB; USPAT; EPO; JPO; DERWENT				
3	US-PGPUB; USPAT; EPO; JPO; DERWENT				
4	US-PGPUB; USPAT; EPO; JPO; DERWENT				
5	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 1	5:43		
6	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 1	7:48		
7	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 1	7:51		
8	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 1	8:38		
1	US-PGPUB; USPAT; EPO; JPO; DERWENT		ŀ		
	US-PGPUB; USPAT; EPO; JPO; DERWENT				
	US-PGPUB; USPAT; EPO; JPO; DERWENT				
12	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 1	8:41		
13	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 1	8:43		
	US-PGPUB; USPAT; EPO; JPO; DERWENT		ľ		
	US-PGPUB; USPAT; EPO; JPO; DERWENT				
	US-PGPUB; USPAT; EPO; JPO; DERWENT				
17	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/09 1:	1:13		
	US-PGPUB; USPAT; EPO; JPO; DERWENT				
19	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18	3:54		

	Errors	Ref #
1		S1
2		S2
3		S3
4		S4
5		S5
6		S6
7		S7
8		S8
9 ·		S9
10		S10
11		S11
12		S12
13		S13
14		S14
15		S16
16		S17
17		S18
18		S19
19		S20

	Type	Hits	Search Text
20	BRS	16	S19 and (motor\$1 actuat\$5) near12 (driv\$5 fiber\$1 fibre\$1)
21	BRS	20440	<pre>(imag\$5 same (illumin\$5 detect\$5 display\$5) same (fiber\$1 fibre\$1))</pre>
22	BRS	16	S21 and S22
23	BRS	12	S23 and (imag\$5 same (screen\$3 display\$4))
24	BRS	851495	<pre>(imag\$5 same (illumin\$5 detect\$5 display\$5))</pre>
25	BRS	360000	<pre>(rotat\$4 same (align\$5 fiber\$1 fibre\$1))</pre>
26	BRS	1635	<pre>(electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)</pre>
27	BRS	3596	(fus\$5 splic\$4 weld\$4) near12 (fiber\$1 fibre\$1) same align\$5
28	BRS	63416	(fiber\$1 fibre\$1) same imag\$4
29	BRS	29	S25 and S26 and S27 and S28 and S29
30	BRS	23	S30 and (display\$4 screen\$3)
31	BRS	16	S31 and (motor\$1 actuat\$5) near12 (driv\$5 fiber\$1 fibre\$1)
32	BRS	20465	<pre>(imag\$5 same (illumin\$5 detect\$5 display\$5) same (fiber\$1 fibre\$1))</pre>
33	BRS	12	S34 and (imag\$5 same (screen\$3 display\$4))
34	BRS	О	S35 and sllid\$4
35	BRS	7	S35 and slid\$4
36	BRS	7	S35 and slid\$6
37	BRS	7	S38 and (motor\$3 actuat\$4 head\$3)
38	BRS	7	S38 and (motor\$4 actuat\$4 head\$3)
39	BRS	1	S43 and head
40	BRS	1	S43 and (lens\$2 head\$4)

	DBs	ŀ	Stamp	Comments	Error Definition
20	US-PGPUB; USPAT; EPO; JPO; DERWENT				
21	US-PGPUB; USPAT; EPO; JPO; DERWENT				
22	US-PGPUB; USPAT; EPO; JPO; DERWENT				
23	US-PGPUB; USPAT; EPO; JPO; DERWENT				
24	US-PGPUB; USPAT; EPO; JPO; DERWENT				
25	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/0	08 10:37		
26	US-PGPUB; USPAT; EPO; JPO; DERWENT				
27	US-PGPUB; USPAT; EPO; JPO; DERWENT				
28	US-PGPUB; USPAT; EPO; JPO; DERWENT				
29	US-PGPUB; USPAT; EPO; JPO; DERWENT				
30	US-PGPUB; USPAT; EPO; JPO; DERWENT				
31	US-PGPUB; USPAT; EPO; JPO; DERWENT				
32	US-PGPUB; USPAT; EPO; JPO; DERWENT				
33	US-PGPUB; USPAT; EPO; JPO; DERWENT				
34	US-PGPUB; USPAT; EPO; JPO; DERWENT				
35	US-PGPUB; USPAT; EPO; JPO; DERWENT				
36	US-PGPUB; USPAT; EPO; JPO; DERWENT				
37	US-PGPUB; USPAT; EPO; JPO; DERWENT				
38	US-PGPUB; USPAT; EPO; JPO; DERWENT				
39	US-PGPUB; USPAT; EPO; JPO; DERWENT				
40	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/0	8 10:50		

	Errors	Ref #
20		S21
21		S22
22		S23
23		S24
24		S25
25		S26
26		S27
27		S28
28		S29
29		S30
30		S31
31		S32
32		S33
33		S35
34		S36
35		S37
36		S38
37		S39
38		S40
39		S44
40		S45

_	Туре	Hits	Search Text
41	BRS	5	S41 and (lens\$2 head\$4)
42	BRS	7	S40 and clamp\$4
43	BRS	3	S41 and head\$3
44	BRS	5	S41 and (cover\$1 (clos\$4 near7 open\$5))
45	BRS	5	S41 and (cover\$4 (clos\$4 near7 open\$5))
46	BRS	16	S32 and S33
47	BRS	14	("20020159724" "5561728" "5013345" "6206583" "6046798" "5904413" "5611015").pn.
48	BRS	7	("20020159724" "5561728" "5013345" "6206583" "6046798" "5904413" "5611015").pn.
49	BRS	12	S31 and S35
50	BRS	7	S50 and S34
51	BRS	2	S52 and actuat\$5
52	BRS	1	"6206583".pn.
53	BRS	1	10/806838
54	BRS	3	S25 and S42
55	BRS	0	S54 and S42
56	BRS	1	S54 and S52
57	BRS	1	S54 and (ax\$4 direct\$4 rotat\$5)
58	BRS	1.	S54 and (ax\$4 direct\$4 rotat\$5 up\$4 low\$4 down)
59	BRS	О	"2000159724"
60	BRS	1	"20020159724"

	DBs		Stamp	Comments	Error Definition
41	US-PGPUB; USPAT; EPO; JPO; DERWENT				
42	US-PGPUB; USPAT; EPO; JPO; DERWENT				
43	US-PGPUB; USPAT; EPO; JPO; DERWENT				
44	US-PGPUB; USPAT; EPO; JPO; DERWENT				
45	US-PGPUB; USPAT; EPO; JPO; DERWENT				
46	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/02/	24 12:40		
47	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/	08 10:57		
48	US-PGPUB; USPAT	2005/09/	08 18:23		
49	US-PGPUB; USPAT	2005/09/	08 10:58		
50	US-PGPUB; USPAT	2005/09/	08 18:33		
51	US-PGPUB; USPAT	2005/09/	08 12:41		
52		2005/09/			
53	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/	08 13:19		
54	US-PGPUB; USPAT	2005/09/	08 13:26		
55	US-PGPUB; USPAT	2005/09/	08 13:27		
56	US-PGPUB; USPAT	2005/09/	08 13:27		
57	US-PGPUB; USPAT	2005/09/	08 13:41		
58	US-PGPUB; USPAT	2005/09/	08 14:00		
59	US-PGPUB; USPAT	2005/09/	08 14:00		
60	US-PGPUB; USPAT	2005/09/	08 15:38		

	ì	
	Errors	Ref #
41		S46
42		S41
43		S42
44		S47
45		S48
46		S34
47		S49
48		S50
49		S51
50		S52
51		S53
52		S54
53		S43
54		S55
55		S56
56		S57
57		S58
58		S59
59		S60
60		S61

	Туре	Hits	Search Text
61	BRS	1	S61 and (dimens\$4 ax\$4 direct\$4 rotat\$5 up\$4 low\$4 down)
62	BRS	1	S61 and (imag\$4 same detect\$5)
63	BRS	1	S43 and (noncoincid\$5 coincident\$5)
64	BRS	1	S61 and (electr\$5 same (imag\$4 display\$4)) and display\$4
65	BRS	1	S61 and ((circui\$4 electr\$5) same (imag\$4 display\$4)) and display\$4
66	BRS	1	S61 and ((circui\$4 electr\$5) and (imag\$4 display\$4))
67	BRS	1	S61 and ((circ\$6 electr\$5) and (imag\$4 display\$4))
68	BRS	1	S61 and ((circ\$6 electr\$5 processc\$5 comput\$4) and (imag\$4 display\$4))
69	BRS	1	S61 and ((circ\$6 electr\$5 processc\$5 comput\$4) same (imag\$4 display\$4))
70	BRS	1	"20020159724"
71	BRS	0	S71 and arc
72	BRS	0	S71 and (electrod\$4 same (electric\$3 char\$4\$4))
73	BRS	1	S71 and (electrod\$4)
74	BRS	1	S75 and arc
75	BRS	1	S75 and (low profil\$4)
76	BRS	4	"6614975".pn.
77	BRS	1	S78 and intensit\$4
78	BRS	1	S75 and (MULTIPLY\$4 fold\$4)
79	BRS	1	S75 and (common same direct\$5 same fiber\$2)
80	BRS	1	S75 and (common near12 (axi\$4 direct\$5) near12 fiber\$2)
81	BRS	7	("20020159724" "5561728" "5013345" "6206583" "6046798" "5904413" "5611015").pn.

	DBs	Time Stamp	Comments	Error Definition
61	US-PGPUB; USPAT	2005/09/08 14:26		
62	US-PGPUB; USPAT	2005/09/08 14:26		
63	US-PGPUB; USPAT; EPO; JPO; DERWENT			
64	US-PGPUB; USPAT; EPO; JPO; DERWENT			
65	US-PGPUB; USPAT; EPO; JPO; DERWENT			
66	US-PGPUB; USPAT; EPO; JPO; DERWENT			
67	US-PGPUB; USPAT; EPO; JPO; DERWENT			
68	US-PGPUB; USPAT; EPO; JPO; DERWENT			
69	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 14:44		
70	US-PGPUB; USPAT	2005/09/08 15:38		
71	US-PGPUB; USPAT	2005/09/08 15:38		
72	US-PGPUB; USPAT	2005/09/08 15:39		
73		2005/09/08 15:39		
74	US-PGPUB; USPAT; EPO; JPO; DERWENT			
75	US-PGPUB; USPAT; EPO; JPO; DERWENT			
76	US-PGPUB; USPAT; EPO; JPO; DERWENT			
77	US-PGPUB; USPAT; EPO; JPO; DERWENT		·	
78	US-PGPUB; USPAT; EPO; JPO; DERWENT			
79	US-PGPUB; USPAT; EPO; JPO; DERWENT			
80	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 17:44		
81	US-PGPUB; USPAT	2005/09/08 18:23		

	Errors	Ref #
61		S62
62		S63
63		S64
64		S65
65		S66
66		S67
67		S68
68		S69
69		S70
70		S71
71		S72
72		S73
73		S74
74		S76
75		S77
76		S78
77		S79
78		S80
79		S81
80		S82
81		S83

	Туре	Hits	Search Text
82	BRS	2	S83 and actuat\$5
83	BRS	1	"6046798".pn.
84	BRS	851495	<pre>(imag\$5 same (illumin\$5 detect\$5 display\$5))</pre>
85	BRS	360000	<pre>(rotat\$4 same (align\$5 fiber\$1 fibre\$1))</pre>
86	BRS	1635	<pre>(electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)</pre>
87	BRS	3596	(fus\$5 splic\$4 weld\$4) near12 (fiber\$1 fibre\$1) same align\$5
88	BRS	63416	(fiber\$1 fibre\$1) same imag\$4
89	BRS	29	S86 and S87 and S88 and S89 and S90
90	BRS	23	S91 and (display\$4 screen\$3)
91	BRS	16	S92 and (motor\$1 actuat\$5) near12 (driv\$5 fiber\$1 fibre\$1)
92	BRS	20465	<pre>(imag\$5 same (illumin\$5 detect\$5 display\$5) same (fiber\$1 fibre\$1))</pre>
93	BRS	16	S93 and S94
94	BRS	7	S96 and S95
95	BRS	1	S85 and S97
96	BRS	1	10/806838
97	BRS	7	("20020159724" "5561728" "5013345" "6206583" "6046798" "5904413" "5611015").pn.
98	BRS	851495	<pre>(imag\$5 same (illumin\$5 detect\$5 display\$5))</pre>
99	BRS	360000	<pre>(rotat\$4 same (align\$5 fiber\$1 fibre\$1))</pre>
100	BRS	1635	<pre>(electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)</pre>
101	BRS	3596	(fus\$5 splic\$4 weld\$4) near12 (fiber\$1 fibre\$1) same align\$5

	DBs	Time Stamp	Comments	Error Definition
82	US-PGPUB; USPAT	2005/09/08 18:32		
83	US-PGPUB; USPAT	2005/09/08 18:32		
84	US-PGPUB; USPAT; EPO; JPO; DERWENT			
85	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 18:33		
86	US-PGPUB; USPAT; EPO; JPO; DERWENT			
87	US-PGPUB; USPAT; EPO; JPO; DERWENT			
88	US-PGPUB; USPAT; EPO; JPO; DERWENT			
89	US-PGPUB; USPAT; EPO; JPO; DERWENT			
90	US-PGPUB; USPAT; EPO; JPO; DERWENT			
91	US-PGPUB; USPAT; EPO; JPO; DERWENT			
92	US-PGPUB; USPAT; EPO; JPO; DERWENT			
93	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 18:33		
94	US-PGPUB; USPAT	2005/09/08 18:34		
95	US-PGPUB; USPAT	2005/09/08 18:34		
96	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 18:35		
97	US-PGPUB; USPAT	2005/10/04 17:45		
98	US-PGPUB; USPAT; EPO; JPO; DERWENT			
99	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/09 11:13		
100	US-PGPUB; USPAT; EPO; JPO; DERWENT			
101	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/09 11:13		

	Errors	Ref #
82		S84
83		S85
84		S86
85		S87
86		S88
87		S89
88		S90
89		S91
90		S92
91		S93
92		S94
93		S95
94		S97
95		S98
96		S75
97		S96
98		S99
99		S100
100		S101
101		S102

	Туре	Hits	Search Text
102	BRS	63416	(fiber\$1 fibre\$1) same imag\$4
103	BRS	29	S99 and S100 and S101 and S102 and S103
104	BRS	4	S104 and (piezo piezoelectric\$4)
105	BRS	1	("20020159724").pn.
106	BRS	1	10/806533
107	BRS	1	S107 and (light near7 inject\$54)
108	BRS	1	S106 and (light near7 (inject\$4 fiber\$1 fbre\$1))
109	BRS	902901	(imag\$5 same (illumin\$5 detect\$5 display\$5))
110	BRS	371496	<pre>(rotat\$4 same (align\$5 fiber\$1 fibre\$1))</pre>
111	BRS	1688	<pre>(electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)</pre>
112	BRS	3723	(fus\$5 splic\$4 weld\$4) near12 (fiber\$1 fibre\$1) same align\$5
113	BRS	65985	(fiber\$1 fibre\$1) same imag\$4
114	BRS	34	S110 and S111 and S112 and S113 and S114
115	BRS	26	S115 and (display\$4 screen\$3)
116	BRS	17	S116 and (motor\$1 actuat\$5) near12 (driv\$5 fiber\$1 fibre\$1)
117	BRS	21552	<pre>(imag\$5 same (illumin\$5 detect\$5 display\$5) same (fiber\$1 fibre\$1))</pre>
118	BRS	17	S117 and S118

	DBs	Time Stamp	Comments	Error Definition
102	US-PGPUB; USPAT; EPO; JPO; DERWENT	1		
103	US-PGPUB; USPAT; EPO; JPO; DERWENT			
104	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/09 11:16		
1		2005/10/04 18:42		
106	US-PGPUB; USPAT; EPO; JPO; DERWENT			
107	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/04 18:37		
		2005/10/04 18:43		
	US-PGPUB; USPAT; EPO; JPO; DERWENT			
110	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/02/24 12:40		
	US-PGPUB; USPAT; EPO; JPO; DERWENT			
	US-PGPUB; USPAT; EPO; JPO; DERWENT			
	US-PGPUB; USPAT; EPO; JPO; DERWENT			
	US-PGPUB; USPAT; EPO; JPO; DERWENT			
	US-PGPUB; USPAT; EPO; JPO; DERWENT			
	US-PGPUB; USPAT; EPO; JPO; DERWENT			
117	US-PGPUB; USPAT; EPO; JPO; DERWENT			
118	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/02/24 12:40		

	Errors	Ref #
102		S103
103		S104
104		S105
105		S106
106		S107
107		S108
108		S109
109		S110
110		S111
111		S112
112		S113
113		S114
114		S115
115		S116
116		S117
117		S118
118		S119